ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: M07625 Alaskan Copper Works Client:

Date Received: 09/08/11 Project: Metro Self Monitor, F&BI 109097

Lab ID: 109097-01 x10 Date Extracted: 09/12/11 Data File: 109097-01 x10.051 Date Analyzed: 09/12/11

Matrix: Water Instrument: ICPMS1 Units: Operator: AP ug/L (ppb)

Lower

Upper Limit: Internal Standard: % Recovery: Limit: Germanium 66 60 125

Concentration

Analyte: ug/L (ppb)

Chromium 249 Nickel 168 Copper 193 Zinc 18.1

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank Client: Alaskan Copper Works

Date Received: Not Applicable Project: Metro Self Monitor, F&BI 109097

Date Extracted: 09/12/11 Lab ID: I1-632 mb Date Analyzed: 09/12/11 Data File: I1-632 mb.043 Matrix: Water Instrument: ICPMS1 Units: ug/L (ppb) Operator: AP

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 65 60 125

Concentration
Analyte: ug/L (ppb)

Chromium <1

Chromium <1
Nickel <1
Copper <5
Zinc <1

ENVIRONMENTAL CHEMISTS

Date of Report: 09/13/11 Date Received: 09/08/11

Project: Metro Self Monitor, F&BI 109097

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 109119-01 (Matrix Spike)

	Reporting	Spike	Sample	Percent Recovery	Percent Recovery	Acceptance	RPD
Analyte	Units	Level	Result	MS	MSD	Criteria	(Limit 20)
Chromium	ug/L (ppb)	20	1.12	102	100	67-132	2
Nickel	ug/L (ppb)	20	1.53	100	98	73-119	2
Copper	ug/L (ppb)	20	31.0	91 b	93 b	50-144	2 b
Zinc	ug/L (ppb)	50	61.3	93 b	94 b	46-148	1 b

Laboratory Code: Laboratory Control Sample

MT 1	Reporting	\mathbf{Spike}	Recovery	Acceptance
Analyte	Units	Level	LCS	Criteria
Chromium	ug/L (ppb)	20	99	66-135
Nickel	ug/L (ppb)	20	100	67-134
Copper	ug/L (ppb)	20	96	66-134
Zinc	ug/L (ppb)	50	91	57-135

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb Analyte present in the blank and the sample.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht Analysis performed outside the method or client-specified holding time requirement.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits.The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve Estimated concentration calculated for an analyte response above the valid instrument calibration range. A dilution is required to obtain an accurate quantification of the analyte.
- vo The value reported fell outside the control limits established for this analyte.
- x The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

AIZ

SAMPLE CHAIN OF CUSTODY

Send Report To. , Gerry Thompson	SAMPLERS (signature)	Page # of TURNAROUND TIME			
Company Alaskan Copper WOTAS Address 628 South Hand Ford	PROJECT NAME/NO. METRO Self monitor	PO#	Standard (2 Weeks) RUSH_4 day Rush charges authorized by:		
City, State, ZIP Seattle, Wa 98134 Phone # 206:571-6033 Fax # 382-4309	PROJECT ADDRESS		SAMPLE DISPOSAL Dispose after 30 days Return samples Will call with instructions		

						L	ANALYSES REQUESTED							
Sample ID	Lab ID	Date Sampled	Time Sampled	Sample Type	# of containers	TPH-Diesel	TPH-Gasoline	BTEX by 8021B	VOCs by 8260	SVOCs by 8270	HFS	CG. 1. 22		Notes
M07625	01	9-8-11	11:30	H20	ŧ	X						X		1 X-pe-
22 55 10542024111 15204	1													proveet squar
					1 1 1 1 1 1 1 1								1	1 11
· 10														
										1				
1-11-11-13-6-44	1													

Friedman & Bruya, Inc. 3012 16th Avenue West Seattle, WA 98119-2029

Ph. (206) 285-8282

Fax (206) 283-5044

FORM	3/CC	ירירנ	אר אחר

SIGNATURE,	PRINT NAME	COMPANY	DATE	TIME
Relinquished by:	Vince Erickson	Alaskan Copper Volks	9-8-11	1250
Received by:	- 1 1/1/2 - 0/2 -	I Ina 7	11 00	1250
Relinquished by:				
Received by:		Samples received at	24 00	

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

September 13, 2011

Gerald Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on September 8, 2011 from the Metro Self Monitor, F&BI 109097 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0913R.DOC